## **Notice**



	IIIII
CORRECTION PRODUCTION CHANGE	
SERVICE FLASH ADD INFORMATION	FILE NO.
Please add this notice to the Service Manual listed below.	REVISION 0
Category: COLOR TELEVISION Date	:FEBRUARY / 07 / 2012
Model: DP32640M Effective from : Chassis NoP32640M-00	
Destination: U.S.A. / CANADA REF : No. SM780169-00	
NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service	
Manual. If the Service Manual Chassis No. does not match	-
Literature is required. This chassis is similar to Chassi difference Service Information is given in this manual. For	· 1

## SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

refer to the Original Service Manual and Notices for Chassis No. P32640-00 used in

## 1. IN THE SERVICE ADJUSTMENTS

Model DP32640 (SM780169).

The are no changes.

## 2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The are no changes.

For parts or service contact:

Sanyo Manufacturing Corporation P.O. Box 2000 3333 Sanyo Road Forrest City, Arkansas 72335-2000

© Sanyo Manufacturing Corporation 2012

February 2012 SMC